

Work required for playground from December 2019 inspections

| Playground:   | Company 1                          | Company 2                |
|---|------------------------------------|--------------------------|
| <b>Rotting timber/ loose fence posts – low risk</b>   | <b>8 ext £640 4 int £320 =£970</b> | <b>15 £1425</b>          |
| Remove all old fencing and add new fencing  | £20,001                            | £10,585                  |
| Remove interior fencing   | £775                               | £1850                    |
| Exposed foundations on wooden trim trail – reinstate – Low risk   | £490                               | inc below (£950)         |
| <b>Missing/damaged bolt covers on wooden trim trail and remove projecting threads</b>   |                                    |                          |
| <b>– replace/fix – low risk</b>   | <b>£25</b>                         | <b>(inc below £1030)</b> |
| <b>Rotted wood on suspension bridge on multisplay – replace affected timbers – low risk</b>   | <b>£63</b>                         | <b>(inc below £950)</b>  |
| Clean/treat moss/algae (making it slippy) on multisplay – low risk  | £200 (inc timber trail)            | £1030 all equip          |
| <b>Evidence of rot in posts, monitor and replace as required – multisplay – low risk</b>  | <b>£425</b>                        | <b>£950</b>              |
| Grass mats are silted up and soil compacted – consider HIC testing impact absorbing to ensure correct surface qualities are maintained. Replace as required – on wooden multisplay – low risk | n/a                                | n/a                      |
| <b>Surface eroded and foundations exposed – reinstate surrounding surfaces – big slide – low risk</b>   | <b>£70</b>                         | inc below                |
| <b>Rotted posts at top of slide – replace effected timbers - low risk</b>   | <b>£85</b>                         | <b>£1100</b>             |
| <b>Painting damaged or worn exposing metal which is rusting – treat and repaint – 2 swings – low risk</b>   | <b>£105</b>                        | <b>£160</b>              |
| <b>Replace bushes, connectors, chains and seats – 2 swings – low risk</b>   | <b>£321.38</b>                     | see below                |
| <b>Replace bushes, connectors, chains and seats – cradle swings – low risk</b>  | <b>£381.71</b>                     | <b>£1730 (both)</b>      |

|   |                       |   |
|---|-----------------------|---|
| <b>Spring mounting plate is slightly loose – monitor and replace as required – spring pig – low risk</b>                            | <b>£100</b>           | <b>tighten and quote if work required</b>   |
| Surface eroded – reinstate – spring pig – low risk  | inc above             | inc below                                   |
| Surface eroded – reinstate – spring tractor – low risk  | £70                   | inc below                                   |
| <b>Spring mounting plate is slightly loose – monitor and replace as required – spring chicken – low risk</b>                        | <b>£100</b>           | <b>as above</b>                             |
| Surface eroded – reinstate – spring chicken – low risk  | inc above             | inc below                                   |
| <u>MUGA:</u>  |                       |   |
| Socket lids not aligned correctly creating potential trip hazards – rectify installation to ensure lid closes flush with the ground |                       |   |
|   | £25                   | n/a   |
| <u>Trim Trail:</u>  |                       |   |
| Various areas to reinstate surface – low risk   | £770                  | £950  |
|   |                       | £1400 carriage and fencing and welfare unit |
| <b>Totals for bold items</b>  | <b>£2296.09 + VAT</b> | <b>£6765+ VAT</b>                           |